



FORMULIR PERMOHONAN PENGAJUAN DANA
UNIVERSITAS NUSA MANDIRI

Diminta oleh :

Kampus	UBSI Dewi Sartika A1	Hari/Tgl. Pengajuan
Pemohon	Elly Krisnawati	02 April 2026
Unit Kerja	Bagian Sarana Prasarana	
No. Rekening Bank dan Nama	2210150598 BCA an Keisha Azaria Putri Yudira	Hari/Tgl. Diperlukan
		08-Apr-26

Keterangan

Jumlah

Bea service lift di Kampus UNM Jatiwaringin bulan Februari 2026	Rp	1.500.000
Total Dana Dibutuhkan :Terbilang#satu juta lima ratus ribu #	Rp	1.500.000

Menyetujui,
Rektor Universitas Nusa Mandiri

Mengetahui,
Ka. BAKU

Pemohon,

(Dr Dwiza Riana, S.Si, MM, M.Kom)
Tanggal :

(Dwi Astuti Ratriningsih, M. Kom)

(Elly Krisnawati)

No. _____
Telah terima dari Univ. Nusa Mandiri, Jab. Wannjin
Uang sejumlah ✓ Satu juta Lima Ratus Ribu Rupiah ✓
Untuk pembayaran perawatan dan peneliharaan 2 unit lift
di umh 71w periode Februari 2026

Datang 08 Maret 2026

Rp. ✓ 1.500.000,- ✓ Eddy


Hai : Penaginan Perawatan KUTIN LIFT

Sehubungan telah dilakukan perawatan lift di Universitas Nusa Mandiri sebanyak 2 unit lift, edisi Bulan Februari 2026.

Harga perawatan
@Rp. 750.000 x 2 unit : Rp. 1.500.000 ✓
Terbilang : Satu Juta Lima Ratus Ribu Rupiah ✓

Bank Transfer
BCA, No. Rek: 2210150598 ✓
a.n: KEISHA AZARIA PUTRI YUDIRA


Hormat Kami,



Eddy

✓
2/4/26

LAPORAN PERAWATAN LIFT
ELEVATOR MAINTENANCE REPORT



Name Of Building : UNU. Nusa Mandiri
Address : Jati Wangin

Date : 14 Februari 2026
Type of Service : Lift. 100.1
Technician : E107

Check List	Remark	Check list	Remark
A Machine Room		C CAR & CWT	
1 Motor	✓	1 Frame Car	✓
2 Gearbox	✓	2 Frame CWT	✓
3 Rubber Pad Mesin	✓	3 Slending Guide	✓
4 Main Sheave	✓	4 Header Car	✓
5 Deflektor Sheave	✓	5 Guide Shoes	✓
6 Sparsator Beam	✓	6 Sill Car	✓
7 Panel Controller	✓	7 Door Operator	✓
8 Wire Rope	✓	8 Indikator	✓
9 Governor	✓	9 Sensor System	✓
10 Oli Gearbox	✓	10 Safety Brake / Block	✓
11 Brake	✓	11 Emergency Exit	✓
		12 Ceiling	✓
B Hoistway		13 Fan	✓
1 Bracket-Bracket	✓	14 Oli Guide Rail	✓
2 Rail Clip	✓	15 Travelling Cable	✓
3 Dynabold	✓	16 Over Load System	✓
4 Guide Rail Car	✓	17 Push Button Cop	✓
5 Guide Rail Cwt	✓		
6 Landing Device	✓		
7 Door Panel	✓	D PIT	
8 Guide Shoes	✓	1 Buffer Car	✓
9 Sill Hall	✓	2 Buffer Cwt	✓
10 Hall Buttons	✓	3 Tension Governor	✓
11 Hall Indikator	✓	4 Switch system Pit	✓
12 Switch System	✓	5 Pit Hoistway	✓
13 Door Lock & Interlock	✓		
14 Bendera Sensor	✓		

Remarks : ✓ Normal Check ○ Lubrikasi
 △ Service/Setting ○ Not Use

note : * Lift. Error E 38 lift manual lisa tpr kaku
 * Running normal h/cek mau.
 * switch lift - rusak (karet dan short)
 * switch panel governor - rusak (karet dan short)


CUSTOMER/ENGINEER/ING DEPT

Alan
Alan

Technician

E107

LAPORAN PERAWATAN LIFT
ELEVATOR MAINTENANCE REPORT



Name Of Building : Univ. Wusa Mandiri
Address : Jat. Waringin.

Date : 28 February 2026
Type of Service : UPT. No. 2
Technician : Ketwo. Gus Sugitono.

Check List	Remark	Check List	Remark
A Machine Room		C CAR & CWT	
1 Motor	✓	1 Frame Car	
2 Gearbox	✓	2 Frame CWT	✓
3 Rubber Pad Mesin	✓	3 Slending Guide	✓
4 Main Sheave	✓	4 Header Car	✓
5 Deflektor Sheave	✓	5 Guide Shoes	✓
6 Sparator Beam	✓	6 Sill Car	✓
7 Panel Controller	✓	7 Door Operator	✓
8 Wire Rope	✓	8 Indikator	✓
9 Governor	✓	9 Sensor System	✓
10 Oil Gearbox	✓	10 Safety Brake / Block	✓
11 Brake	✓	11 Emergency Exit	✓
		12 Ceiling	✓
B Holstway		13 Fan	✓
1 Bracket-Bracket	✓	14 Oli Guide Rail	✓
2 Rail Clip	✓	15 Travelling Cable	✓
3 Dynabold	✓	16 Over Load System	✓
4 Guide Rail Car	✓	17 Push Button Cop	✓
5 Guide Rail Cwt	✓		
6 Landing Device	✓	D PIT	
7 Door Panel	✓	1 Buffer Car	✓
8 Guide Shoes	✓	2 Buffer Cwt	✓
9 Sill Hall	✓	3 Tension Governor	✓
10 Hall Buttons	✓	4 Switch system Pit	✓
11 Hall Indikator	✓	5 Pit Holstway	✓
12 Switch System	✓		
13 Door Lock & Interlock	✓		
14 Bendera Sensor	✓		

Remarks : ✓ Normal Check
Δ Service/Setting
L Lubrikasi
o Not Use

Note :
* Perawatan di pelumas main hall. dan lift hall.
* Check Room Panel Control dan Motor Traction
* Spring parts shaft Lt. 2 dan Lt. 5. sudah getas

CUSTOMER/ENGINEERING DEPT.
Agus

Teknisi
Eidy



